

## Facility Registry System (FRSOH)

MAP ID# 1

Distance from Property: 0.00 mi. N

### FACILITY INFORMATION

REGISTRY ID: 110009008750

NAME: LISBON BRD OF PUBLIC AFFAIRS WTP

LOCATION ADDRESS: 8077 STATE RTE 164  
LISBON, OH 44432

COUNTY: COLUMBIANA

EPA REGION: 05

FEDERAL FACILITY: NOT REPORTED

TRIBAL LAND: NOT REPORTED

#### ALTERNATIVE NAME/S:

LISBON BRD OF PUBLIC AFFAIRS WTP

LISBON BOARD OF PUBLIC AFF WTP

#### PROGRAM/S LISTED FOR THIS FACILITY

OH-CORE - \*DEFINITION NOT PROVIDED BY REPORTING AGENCY

NPDES - NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM

#### STANDARD INDUSTRIAL CLASSIFICATION/S (SIC)

4941 - WATER SUPPLY

4941 - WATER SUPPLY

4941 - WATER SUPPLY

#### NORTH AMERICAN INDUSTRY CLASSIFICATION/S (NAICS)

NO NAICS DATA REPORTED

---

[Back to Report Summary](#)

## Facility Registry System (FRSOH)

MAP ID# 1

Distance from Property: 0.00 mi. N

### **FACILITY INFORMATION**

REGISTRY ID: 110006343108

NAME: LISBON WATER DEPARTMENT

LOCATION ADDRESS: 8077 STATE RTE 164  
LISBON, OH 44432-9383

COUNTY: COLUMBIANA

EPA REGION: 05

FEDERAL FACILITY: NOT REPORTED

TRIBAL LAND: NOT REPORTED

#### ALTERNATIVE NAME/S:

LISBON WATER DEPARTMENT

LISBON VILLAGE

LISBON VILLAGE-LISBON WATER DEPARTMENT

#### PROGRAM/S LISTED FOR THIS FACILITY

OH-CORE - \*DEFINITION NOT PROVIDED BY REPORTING AGENCY

SFDW - \*DEFINITION NOT PROVIDED BY REPORTING AGENCY

SFDW - \*DEFINITION NOT PROVIDED BY REPORTING AGENCY

#### STANDARD INDUSTRIAL CLASSIFICATION/S (SIC)

NO SIC DATA REPORTED

#### NORTH AMERICAN INDUSTRY CLASSIFICATION/S (NAICS)

NO NAICS DATA REPORTED

---

[Back to Report Summary](#)

# **Integrated Compliance Information System National Pollutant Discharge Elimination System (ICISNPDES)**

**MAP ID# 1**

Distance from Property: 0.00 mi. N

## **FACILITY INFORMATION**

NPDES ID: **OH0083682INPDES** FACILITY #: **110009008750**

NAME: **LISBON BRD OF PUBLIC AFFAIRS WTP**

PHYSICAL ADDRESS: **8077 STATE RTE 164**

**LISBON OH 44432**

COUNTY: **COLUMBIANA**

FACILITY TYPE: **PRIVATELY OWNED FACILITY**

IMPAIRED WATERS: **NOT REPORTED**

## **STANDARD INDUSTRIAL CLASSIFICATION**

**4941-WATER SUPPLY**

## **PERMITS**

FACILITY TYPE INDICATOR: **NON-POTABLE WATER**

PERMIT TYPE: **NPDES INDIVIDUAL PERMIT**

MAJOR MINOR FACILITY: **MINOR**

PERMIT STATUS: **EFFECTIVE**

WATER BODY: **MILL SITE CREEK**

PERMIT NAME: **LISBON BOARD OF PUBLIC AFFAIRS**

AGENCY TYPE: **STATE**

ORIGINAL ISSUE DATE: **10/31/1990**

ISSUE DATE: **05/13/2014**

ISSUING AGENCY: **NOT REPORTED**

EFFECTIVE DATE: **06/01/2014**

EXPIRATION DATE: **05/31/2019**

RETIREMENT DATE: **NOT REPORTED**

TERMINATION DATE: **NOT REPORTED**

PERMIT COMPLIANCE STATUS: **NOT REPORTED**

PERMIT SUBJECT TO DMR RUN: **YES**

REPORTABLE NONCOMPLIANCE TRACKING IS ON: **YES**

## **INSPECTIONS**

MONITOR TYPE: **EVALUATION**

LEAD AGENCY: **STATE**

ACTUAL BEGIN DATE: **NOT REPORTED**

ACTUAL END DATE: **08/10/2010**

MONITOR TYPE: **EVALUATION**

LEAD AGENCY: **STATE**

ACTUAL BEGIN DATE: **NOT REPORTED**

ACTUAL END DATE: **03/22/2007**

MONITOR TYPE: **EVALUATION**

LEAD AGENCY: **STATE**

ACTUAL BEGIN DATE: **01/23/2014**

## Emergency Response Notification System (ERNSOH)

MAP ID# 1

Distance from Property: 0.00 mi. N

### INCIDENT INFORMATION

GSID#: 416964

NRC ID#: 416964

INCIDENT LOCATION: NOT REPORTED

INCIDENT ADDRESS: 8077 STATE ROUTE 164  
LISBON, OH 44432

INCIDENT COUNTY: COLUMBIANA

### INCIDENT DETAILS

INCIDENT DATE: 10/22/1997 2:30:00 AM

INCIDENT CAUSE: UNKNOWN

INCIDENT TYPE: FIXED

INCIDENT OCCURED/DISCOVERED: OCCURRED

INCIDENT DESCRIPTION: MAINTENANCE BUILDING-GARAGE/SUSPECTED MALFUNCTIONING GAS HEATER IN GARAGE  
CAUSED FIRE TO BURN THE BUILDING (TOTAL LOSS)/RELEASED CHLORINE

### RESPONSIBLE PARTY

RESPONSIBLE COMPANY: LISBON WATER DEPARTMENT

ADDRESS: ADDRESS NOT REPORTED  
LISBON OH 44432

RESPONSIBLE COMPANY ORGANIZATION TYPE: PUBLIC UTILITY

### MATERIALS INVOLVED

CHRIS CODE: CLX

MATERIAL REACHED WATER: YES

WATER AMOUNT: UNKNOWN AMOUNT / NOT REPORTED

MATERIAL RELEASED/AMOUNT: CHLORINE / 150 POUND(S)

### OTHER MATERIALS INVOLVED

- NO OTHER MATERIALS INVOLVED -

### REMEDIAL ACTION

REMEDIAL ACTION: FIRE EXTINGUISHED, LOCAL HAZMAT RESPONSE TEAM CONTAINED REMAINING CYLINDERS

---

[Back to Report Summary](#)